

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Fig. 1




Fig. 2




Fig. 3




Fig. 4a




Fig. 4b




Fig. 5




Fig. 6




Fig. 7






Fig. 8a Fig. 8b Fig. 8c Fig. 8d Fig. 8e

Fig. 10




Fig. 11




Fig. 12?




Fig. 13a




Fig. 13b




Fig. 14a




Fig. 14b





Fig. 15a




Fig. 15b




Fig. 16a




Fig. 16b




Fig. 17a




Fig. 17b




Fig. 18




Fig. 19




Fig. 20




Fig. 21




Fig. 222

The diagram illustrates a mechanical assembly with several key components labeled as follows:

- 2393**: A large rectangular frame or housing.
- 2394**: Two circular features, possibly rollers or guides, positioned at the top corners of the frame.
- 2373**: A vertical support post located near the center.
- 2374**: A component mounted on the vertical post, featuring a series of horizontal lines.
- 2343**: A horizontal bar or plate extending from the central post towards the right side.
- 2346**: A horizontal bar or plate extending from the left side towards the center.
- 2344**: A bracket-like structure at the bottom left corner.
- 2342'**: A long horizontal bar spanning most of the width of the assembly.
- 2311**: A rectangular block resting on the lower surface of the 2342' bar.
- L'**: A label indicating a length or distance along the bottom edge.
- R'**: A label indicating a radius or curved dimension on the right side.
- 2340**: An irregular shape at the bottom right, possibly representing a base or a specific material section.

